



December 1893  
I commenced Survey of Section  
18 Town 7 North,  
Range 4 West.  
E. F. K. out  
for F. M. Parker  
County Surveyor  
Deputy

Corners Established.	Monument.	Bearing Trees.	Diameter in Inches.	Course.	Links Distant.
center 1/4	Stone	ash	12	N 50 E	104
S 1/4 S W	Stone				
N 1/4 S W	Stone				
cen S W	Stone	Sycamore	10	N 42 1/2 E	82
N 1/4 N W	Stone	Gum	18	N 57 E	14
cen N E	Stone	Bl Walnut	15	S 43 E	90
cen S E	Stone	Mulberry	10	S 38 1/2 E	13
W 1/4 N E	Stone	Locust	5	S 52 1/2 E	82
cen N W	Stone	Bl Oak	15	N 55 W	9 1/2
W 1/4 N W	Stone	ash	12	N 53 E	24

COURSE.	DISTANCE.	REMARKS.	
West	25.25	From N E corner 18	
	40.09	to Richland creek	
	77.00	to N 1/4	
South		N W at the corner	2° 30'
	39.92	From N 1/4	
	55.00	center	
	79.50	Richland creek	
West-		S 1/4 138 lbs W	4°
		From S E	
	19.93	1/4 1/4 corner	
	39.72	1/4 corner	
	64.50	Richland creek	
	77.34	S W 8 lbs South	2°
West		From E 1/4	
	11.00	cen creek	
	39.74	center 1/4	
	77.44	N 1/4	2° 10'
North		lap 241 lbs	
	4.00	From S 1/4 S W.	
South	39.50	cen creek	3° 45'
	7.50	N 1/4 S W	
	16.00	From N 1/4 N E	
	20.02	creek (Richland)	
	30.00	road bridge 50 feet East	3° 43'
South	39.77	S 1/4 N E	
		Richland creek	
		From N 1/4 S E	
		S 1/4 S E	